ECS Configuration Change Request

1. Originator	2. Log Date:	3. CCR #:	4. Rev:	5. Tel:	6. Rm #:	7. Dept.
Michelle Garrett	5-11-00	00-0526	–	(301) 925-0537	2044H	SED/CM

8. CCR Title: Incorporate COTS, Compiler and Solaris OS Patch baseline changes to the (5A) DAACs, (5B-I) VATC and (5B) PVC

9. Originator Signature/Date	10. Class	11. Type:	12. Need Date: 5/15/00
Michelle Garrett 5/11/00	II	CCR	

13. Office Manager Signature/Date	14. Category of Change:	15. Priority: (If "Emergency" fill in Block 28).
Wanda Jones Brown 5/11/00	Update ECS Baseline Doc.	Routine

16. Documentation/Drawings Impacted:	17. Schedule Impact:	18. CI(s) Affected:
910-TDA-003, 910-TDA-005, 920-TDx-002, 920-TDP-002, 920-TDV-002, 920-TDx-014, 920-TDV-014, 920-TDP-014	Audit	

19. Release Affected by this Change:	20. Date due to Customer:	21. Estimated Cost:
5A, 5B		None - Under 100K

22. Source Reference: ☐NCR (attach) ☒Action Item ☐Tech Ref. ☐GSFC ☐Other:
CCR 00-0316/AC-0342/0343, CCR 00-0327/AC-0351, CCR 00-0352/AC-0399, CCR 00-0357/AC-0358, CCR 00-0358/AC-0369/0370, CCR 00-0362/AC-0392, CCR 00-0457/AC-0463, CCR 00-0458/AC-00-0466, CCR 00-0461/AC-0475/0477

23. Problem: (use additional Sheets if necessary)
Documentation change to update the COTS SW Version B/L, HW-SW Maps, HW Patch Maps and Site-Host Map with the following: (1) upgrade Netscape Comm. to 4.7 for VATC, (2) add new Catalyst 6000 & Hosts to VATC, (3) update Purify 4.5.1 for Solaris 2.5.1, (4) add Sybase Replication Server Manager 11.5.1, Replication Server 11.5.1 & Sybase Central 3.0.0 to p0dms03, (5) upgrade JRE to 1.2.1 & install OS Patch for VATC & PVC, (6) upgrade Visual Workshop to 3.0 & Fortran 77 to 4.2 & install Compiler Patches, (7) upgrade HP OV to 6.0 & add OS Patch, (8) upgrade Netscape Comm. to 4.7 for DAACs and (9) upgrade JRE to 1.2.1 for DAACs.

24. Proposed Solution: (use additional sheets if necessary)
Implement above changes in XRP as delineated in Section 23.

25. Alternate Solution: (use additional sheets if necessary)
None.

26. Consequences if Change(s) are not approved: (use additional sheets if necessary)
5/11 ~~Impacts ECS Baseline if not approved.~~
Document does not reflect the configuration of the system.

27. Justification for Emergency (If Block 15 is "Emergency"):

28. Site(s) Affected: ☐EDF ☐PVC ☐VATC ☐EDC ☐GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL ☐EOC ☐IDG Test Cell ☐Other

29. Board Comments:	30. Work Assigned To:	31. CCR Closed Date:

32. EDF/SCDV CCB Chair (Sign/Date): Bryan V Peters 5/15/00	**Disposition:** Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
33. M&O CCB Chair (Sign/Date):	**Disposition:** Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
34. ECS CCB Chair (Sign/Date):	**Disposition:** Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS

ORIGINAL

ADDITIONAL SHEET

CCR #: 00-0526 **Rev:** **Originator:** Michelle Garrett

Telephone: (301) 925-0537 **Office:** 2044H

Title of Change: Incorporate COTS, Compiler and Solaris OS Patch baseline changes to the (5A) DAACs, (5B-I) VATC and (5B) PVC

The following updates are being incorporated into the 5A and 5B baselines. Each change is briefly described in block 23.

(1) CCR 00-0316, dated 3/24/00, affecting 910-TDA-003 (5B-I) Rev 45 dated 5/15/00 and 920-TDV-002 (5B-I) Rev 23 dated 5/15/00.
(2) CCR 00-0327 dated 3/2700, affecting 910-TDA-005 (5A) Rev 19 dated 5/15/00 and 920-TDV-002 (5B-I) Rev 23 dated 5/16/00.
(3) CCR 00-0352, dated 3/29/00, affecting 910-TDA-003 (5A) Rev 44 dated 5/15/00; 910-TDA-003 (5B) Rev 46 dated 5/15/00; 920-TDx-002 (5A) dated 5/15/00 and 920-TDP-002 (5B) Rev 12 dated 5/15/00.
(4) CCR 00-0357, dated 3/30/00, affecting 910-TDA-003 (5B) Rev 46, dated 5/15/00 and 920-TDP-002 (5B) Rev 12 dated 5/15/00.
(5) CCR 00-0358 dated 3/31/00, affecting 910-TDA-003 (5B-I) Rev 45 dated 5/15/00; 910-TDA-003 (5B) Rev 46 dated 5/15/00 920-TDV-002 (5B-I) Rev 23 dated 5/15/00 and 920-TDP-002 (5B) Rev 12 dated 5/15/00.
(6) CCR 00-0362, dated 3/31/00, affecting 910-TDA-003 (5A) Rev 44 dated 5/15/00; 910-TDA-003 (5B-I) Rev 45 dated 5/15/00; 910-TDA-003 (5B) Rev 46 dated 5/15/00; 920-TDx-002 (5A) dated 5/15/00; 920-TDV-002 Rev 23 dated 5/15/00; 920-TDP-002 (5B) Rev 12 dated 5/15/00; 920-TDx-014 (5A) dated 5/15/00; 920-TDA-014 (5B-I) Rev 4 dated 5/15/00 and 920-TDP-014 (5B) Rev 01 dated 5/15/00.
(7) CCR 00-0457 dated 4/26/00, affecting 910-TDA-003 (5A) Rev 44 dated 5/15/00; 920-TDx-002 (5A) dated 5/15/00; 920-TDx-014 (5A) dated 5/15/00; 920-TDA-014 (5B-I) Rev 4 dated 5/15/00 and 920-TDP-014 (5B) Rev 01 dated 5/15/00.
(8) CCR 00-0458 dated 4/26/00, affecting 910-TDA-003 (5A) Rev 44 dated 5/15/00; 910-TDA-003 (5B-I) Rev 45 dated 5/15/00; 920-TDx-002 (5A) dated 5/15/00; 920-TDV-002 Rev 23 dated 5/15/00.
(9) CCR 00-0461 dated 4/27/00, affecting 910-TDA-003 (5A) Rev 44 dated 5/15/00; 920-TDE-002 (5A) Rev 17 dated 5/15/00; and 920-TDE-014 Rev 05 dated 5/15/00.

Document Name	From	To
Hardware -Software Map, PVC Subsystem B/L 5B	920-TDP-002 Rev 11	920-TDP-002 Rev 12
Hardware-Software Map, VATC Subsystem B/L, 5B (Interim)	920-TDV-002 Rev 22	920-TDV-002 Rev 23
Hardware-Software Map, EDC Operational Subsystem B/L 5A	920-TDE-002 Rev 16	920-TDE-002 Rev 17
Hardware-Software Map, GSFC Operational Subsystem B/L 5A	920-TDG-002 Rev 17	920-TDG-002 Rev 18
Hardware-Software Map, LaRC Operational Subsystem B/L 5A	920-TDL-002 Rev 16	920-TDL-002 Rev 17
Hardware-Software Map, NSIDC Operational Subsystem B/L 5A	920-TDN-002 Rev 15	920-TDN-002 Rev 16
Hardware-Software Map, SMA Operational Subsystem B/L 5A	920-TDS-002 Rev 15	920-TDS-002 Rev 16
Hardware-Patch Map, ECS-wide Operational Subsystem B/L. 5B	920-TDP-014 Rev 00	920-TDP-014 Rev 01
Hardware-Patch Map, VATC Subsystem B/L, 5B (Interim)	920-TDV-014 Rev 03	920-TDV-014 Rev 04
Hardware-Software Map, EDC Operational Subsystem B/L 5A	920-TDE-014 Rev 04	920-TDE-014 Rev 05
Hardware-Software Map, GSFC Operational Subsystem B/L 5A	920-TDG-014 Rev 05	920-TDG-014 Rev 06
Hardware-Software Map, LaRC Operational Subsystem B/L 5A	920-TDL-014 Rev 05	920-TDL-014 Rev 06

ORIGINAL

Hardware-Software Map, NSIDC Operational Subsystem B/L 5A	920-TDN-014 Rev 04	920-TDN-014 Rev 05
COTS Software Version Baseline Report ECS-wide Subsystem B/L, Drop 5A	910-TDA-003 Rev 38	910-TDA-003 Rev 44
COTS Software Version Baseline Report ECS-wide Subsystem B/L Drop 5B (Interim)	910-TDA-003 Rev 41	910-TDA-003 Rev 45
COTS Software Version Baseline Report ECS-wide Subsystem B/L Drop 5B	910-TDA-003 Rev 43	910-TDA-003 Rev 46
Site-Host Map Report, ECS-wide Subsystem B/L, Drop 5A	910-TDA-005 Rev 17	910-TDA-005 Rev 19

CM01AJA00

ORIGINAL