

ECS Configuration Change Request

CCR No. <u>97-1732</u>	Logged Date <u>12/17/97</u>	Rev. <u>-</u>	Request Type <u>CCR</u>
Priority Routine <input type="checkbox"/> Urgent <input type="checkbox"/> Emergency <input checked="" type="checkbox"/>	Affected Release <u>B</u>	Change Class <u>II</u>	

Title Installing PATCH 2458 on SGLs in IDG Cell for on Thursday and if it fixes the problem specified below it should be installed on the EDF, miniDAACS, VATC and DAACS on Friday.

Documents Affected <u>None</u> <u>N/A</u>	Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tec Reference <u>N/A</u>
----------------------------------------------	-----------------------------------------------------------------------------------

RTM Change Start New Baseline

Problem
Applications which require a large shared library to load during their startup crash because of rld(run time linker) problem.
(C/LESG: & DR PEPPER)

Proposed Solution
This can be fixed by installing PATCH # 2458 whose sole purpose is to fix the above said problem..
Need, 12/18/97

Impact Analysis

Organizations Affected:

Cost: <input type="checkbox"/>	BOO <input type="checkbox"/>	Contracts <input type="checkbox"/>	ECS Chief Eng <input type="checkbox"/>	FOS <input type="checkbox"/>	M&O <input type="checkbox"/>
Schedule: <input type="checkbox"/>	Security <input type="checkbox"/>	Rel. Dev <input checked="" type="checkbox"/>	Rel. A <input type="checkbox"/>	Rel. C <input type="checkbox"/>	SCDO Arch. <input type="checkbox"/>
Additional LOC	None <input checked="" type="checkbox"/>	Small <input type="checkbox"/>	Medium <input type="checkbox"/>	Large <input type="checkbox"/>	
Materials					

Originator Signature Vidya Sagar SRE Vidya Sagar Man-Months _____
Office _____ Date 12/17/97

Disposition
Comments: _____ Office Manager R. S. Suman 12/17/97
Approved Approved w/Comment Forward Disapproved
Signature _____ Date _____

CM01OC96 _____ 12/18/97 ECS

ORIGINAL